

**Familia 02556 – Accesorios cobre rigido frigorista**



Codigo	Denominacion Articulo	Udes/Caja
<a href="#">025156</a>	<a href="#">CURVA H/H 1/4" 90° '2A cu.</a>	10
<a href="#">025149</a>	<a href="#">CURVA H/H 3/8" 90° '2A cu.</a>	25
<a href="#">025150</a>	<a href="#">CURVA H/H 1/2" 90° '2A cu.</a>	25
<a href="#">025151</a>	<a href="#">CURVA H/H 5/8" 90° '2A cu.</a>	25
<a href="#">025152</a>	<a href="#">CURVA H/H 3/4" 90° '2A cu.</a>	25
<a href="#">025153</a>	<a href="#">CURVA H/H 7/8" 90° '2A cu.</a>	10
<a href="#">025157</a>	<a href="#">CURVA H/H 1" 90° '2A cu.</a>	10
<a href="#">025154</a>	<a href="#">CURVA H/H 1" 1/8" 90° '2A cu.</a>	10
<a href="#">025158</a>	<a href="#">CURVA H/H 1" 3/8" 90° '2A cu.</a>	5
<a href="#">025155</a>	<a href="#">CURVA H/H 1" 5/8" 90° '2A cu.</a>	5



Accesorio de cobre frigorífico en pulgadas para soldar. Conforme a la Norma ASME B16.22-2011.

